## HISTORIC AMERICAN ENGINEERING RECORD

## Index to Photographs

Addendum to:

Hacienda Azucarera La Esperanza: Mill (Ruins)
(La Esperanza Sugar Plantation: Mill (Ruins)
2.65 miles N of PR Route 2 bridge
over Manati River

HAER NO. PR-1B

Tierras Nuevas Poniente MANATI Municipality of Manati Puerto Rico

NOTE: These photographs are U.S. Government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer, Jack Boucher, would be appreciated. All photographs were taken by Jack Boucher in August 1977.

PR-1B-1	Distant view of sugar mill ruins looking W.
PR-1B-2	View of sugar mill ruins looking N showing chimney at left and masonry base of steam engine and cane mill at right.
PR-1B-3	View of partially excavated mill ruins looking NW showing unidentified pit in right foreground, masonry base for steam engine and cane mill in left center, purging house and chimney in background.
PR-1B-4	View of mill ruins looking S.
PR-1B-5	View looking E at unidentified archeological feature - possibly the underground flue leading from Jamaican Train to chimney.
PR-1B-6	View of mill wall ruins looking E showing arched openings where fuel was fed to fire Jamaican Train.
PR-1B-7	Detail view of mill wall ruins looking E showing arched openings for Jamaican Train and archeological excavations at base of wall.
PR-1B-8	General view looking S at archeological excavations along base of west wall of purging house.
PR-1B-9	View looking S at archeological excavations at base of wall adjacent to Jamaican Train.
PR-1B-10	View looking S at large arched opening that led from area where Jamaican Train was fired to steam engine and cane mill.

Hacienda La Esperanza: Mill Ruins HAER No. PR-1B Index to Photographs Page 2

PR-1B-11	View looking from opposite direction (N) at arched opening depicted in previous view.
PR-1B-12	Detail view of unidentified opening in wall of mill.
PR-1B-13	Detail view of arched opening where fuel was fed to fire Jamaican Train.
PR-1B-14	Detail view of passageway under wall of mill.
PR-1B-15	View looking N at foundation ruins of steam engine and cane mill.
PR-1B-16	View looking E at foundation ruins of steam engine and cane mill.
PR-1B-17	View looking E at steam engine flywheel pit.
PR-1B-18	View of archeological excavations along base of mill wall showing unidentified pits.
PR-1B-19	View looking N at mill wall ruins with open end of purging house in background.
PR-1B-20	View of open end of purging house looking N.
PR-1B-21	View of interior of purging house looking N showing roof trussing.
PR-1B-22	Detail interior veiw of window opening and non-original column supporting roof truss in purging house.
PR-1B-23	Detail view of cornice on NE corner of purging house.
PR-1B-24	Detail view of deteriorated brick work of purging house.
PR-1B-25	View of chimney with mill wall ruins in background looking S.
PR-1B-26	View of chimney looking N.
PR-1B-27	View of chimney base looking N.
PR-1B-28	Detail view of chimney base looking N.
PR-1B-29	View of stone wall ruins of slave quarters.
PR-1B-30	n

## HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

HAER PR 55-MANA, 110-

ADDENDUM TO
HACIENDA AZUCARERA LA ESPERANZA, MILL (RUINS)
(La Esperanza Sugar Plantation, Mill (Ruins)
N. of Route 2 Bridge over Manati River
Manati
Municipality of Manati
Puerto Rico

HAER No. PR-1B (p. 3)

PR-1B-1 through PR-1B-30 were previously transmitted to the Library of Congress.

## INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, August 1977

PR-1B-31 (CT) VIEW OF SUGAR MILL RUINS LOOKING NORTH SHOWING CHIMNEY AT LEFT AND MASONRY BASE OF STEAM ENGINE AND CANE MILL AT RIGHT

PR-1B-32 (CT)

VIEW OF PARTIALLY EXCAVATED MILL RUINS LOOKING NORTHWEST SHOWING UNIDENTIFIED PIT IN RIGHT FOREGROUND, MASONRY BASE FOR STEAM ENGINE AND CANE MILL IN LEFT CENTER, PURGING HOUSE AND CHIMNEY IN BACKGROUND